DETAILED ACTION

Continued Examination Under 37 CFR 1.114

A request for continued examination under 37 CFR 1.114, including the fee set forth in 37 CFR 1.17(e), was filed in this application after final rejection. Since this application is eligible for continued examination under 37 CFR 1.114, and the fee set forth in 37 CFR 1.17(e) has been timely paid, the finality of the previous Office action has been withdrawn pursuant to 37 CFR 1.114. Applicant's submission filed on 10/25/10 has been entered.

EXAMINER'S AMENDMENT

An examiner's amendment to the record appears below. Should the changes and/or additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR 1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the payment of the issue fee.

Authorization for this examiner's amendment was given in a telephone interview with Steve Jensen on 12/10/10.

The application has been amended as follows:

In claim 10, line 1, --pipe-- has been inserted before "connector".

In claim 10, line 2, --pipe-- has been inserted before each instance of "part".

In claim 24, line 2, the phrase "forming at least one" has been replaced with -- selected from the group consisting--.

In claim 27, line 1, --pipe-- has been inserted before "connector".

In claim 27, lines 1-2, the phrase "between at least on female part and at least one male part" has been deleted.

In claim 27, line 3, "the female part" has been replaced with --a female pipe part--

.

In claim 27, line 3, "the male part" has been replaced with --a male pipe part--. In claim 34, line 2, --pipe-- has been inserted before each instance of "part". In claim 34, line 4, "and" has been deleted.

Any inquiry concerning this communication or earlier communications from the examiner should be directed to JAMES M. HEWITT whose telephone number is (571)272-7084. The examiner can normally be reached on M-F, 930am-600pm.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Daniel Stodola can be reached on 571-272-7087. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Application/Control Number: 10/587,597 Page 4

Art Unit: 3679

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

/James M Hewitt/
Primary Examiner, Art Unit 3679